



Powering Hope
and
Possibilities

IMR – CMR
Maintenance
Projects
2023-2024

Before

After



Brentwood
Classroom Flooring

Carseland Boiler Replacement



Before



After

Before



After



Flooring Replacement
CMJHS

Hallway Floor Replacement Carseland



Before



After



Before



After

DVSS Fire Door

DVSS Adiabatic Water Chiller



DVSS

Adiabatic Water Chiller

Before

After



DVSS Staff Room Remodel



Before



After



Before



After

Dr Elliott Ceiling and Lighting Upgrades

Before



After



Greentree Classroom Ceiling Replacement
and Lighting Upgrade

Greentree Floor Replacement



Before



After

Sanitary Lines Replacement

SHS



Old



New



Old



New

Before



After



Theatre Carpet & Chairs Replacement
SHS

Washroom Replacement - Before SHS



Washroom Replacement - After SHS




Strathmore Dorms Roof Replacement



Before



After



Before



After

Washroom Flooring Upgrade

TCA

TCA Addition – Administration Area



Before



After



TCA
Ceiling and Lighting Upgrades

Countertops – Gym Washrooms Three Hills



Before



After

Before




After



Flooring Replacement
Three Hills School

Wheatland Elementary New Library Carpet



Before



After

Wheatland Elementary Barrier Free Washroom Door Controls



Gas Meter and Water Room Heater Replacement – Wheatland Elementary



Before



After

Wheatland Elementary AHU Motor Replacement

Before

After



Before



After



Wheatland Crossing
Classroom Lighting Upgrades



Wheatland Crossing Replace Braided Heating Lines

Wheatland Crossing Fitness Centre



Acme School	Drainage –Erosion Control	DVSS	Plumbing Upgrades	Greentree	Fence Replacement
Brentwood	Repaved Tarmac	DVSS	P/A Power Supply Board	Greentree	Replace Lift Electrical Contactors
Carbon School	Lighting Upgrades	DVSS	Replace Cable and Safety Strap Device	Greentree	BMS Upgrade
Carseland School	Replace Glycol Loop Switch	DVSS	Kitchen Upgrades	Greentree	Emergency Lights
Carseland School	Replace Emergency Light Packs	DVSS	LED Light Upgrades- Phase 2	Greentree	Replace Unsafe Flag Pole
Carseland	Lighting Upgrades	DVSS	Heat Pumps	Greentree	Replace Broken PA Speaker
CMJHS	Fire Sprinkler System	DVSS	Gym Floor Carryover	PCA	Security Upgrades
CMJHS	Main Breaker Replacement	Dr. Elliott	Electrical for Woodshop	PCA	Replacement Backstop Safety Device
CMJHS	Paving	Dr. Elliott	Pump Valve Actuator	PCA	VFD AHU 1&2
CMJHS	Washroom Upgrades	Dr. Elliott	Carryover BMS Upgrade	PCA	Window Replacement
CMJHS	Glycol Pump Motor Replacement	George Freeman	Fire Sprinkler System	SHS	Replace Flush Valves
CMJHS	HVAC RTU Motors	George Freeman	Replace Air Handler 1 Heating Coil	SHS	Electrical Upgrades Welding Shop
CMJHS	Replace Door Strike	George Freeman	Replacement Door Operator	SHS	Fire Sprinkler System
DVSS	Replace Flame Control Board	George Freeman	Flooring Replacement	SHS	Replace Boiler Flow Switch & Glycol Pump Seal
DVSS	Fire Sprinkler	George Freeman	Metal Flashing Installed	SHS	Replace Barrier Free Front Door Button

SHS	Replace Grease Trap	Westmount	Lighting Upgrades
SHS	Replace Basketball Backstop Winch	Westmount	Bathroom Partitions
SHS	Exterior Light Upgrades	Westmount	Replace Economizer on RTU 6
SHS	Hydraulic Heater Replacement	Wheatland Elm	Replace Lift Mechanic Parts
Three Hills	PA System Upgrade	Wheatland Elm	Replace unsafe Flag Pole
Three Hills	Replace RTU Gas Valve	Wheatland Elm	Install VFD
TCA	HVAC- Install Reheat Coil in VAV	Wheatland Elm	Replace Fire Sprinkler Mechanics
TCA	Boiler Pump	Wheatland Elm	Barrier Free Washroom Door
Trochu	VFD AH1&2	Wheatland Crossing	Replace Fire Pumps Sprinkler Parts
Trochu	Replace Electric Door Strikes	Wheatland Crossing	Backflow Preventor
Trochu	Lighting Upgrades	Wheatland Crossing	Replacement Door Hinges
Westmount	Flooring Replacement	Wheatland Crossing	Replace Classroom Door